



Fix A Carb Ltd
52 Eastgate
Station Approach
Woking
GU22 7PQ
Tel: 07875300056
Email: sales@fixacarb.co.uk

SU Carburettor Reconditioning Price List – May 2018

Type	Retail Price (GBP)*	Surcharge (GBP)
Single HS4 non waxstat	£115	£35
Single HS2	£110	£35
Single HS4 waxstat	£139	£28
Single HS6 non waxstat	£110	£60
Single HS6 waxstat	£139	£60
Twin HS2	£199	£95
Twin HS4 non waxstat	£199	£125
Twin HS4 waxstat	£243	£125
Twin HS6 non waxstat	£212	£120
Twin HS6 Waxstat	£243	£120
Twin H1/2/4/6	£342	£400
Single HIF38 or HIF44 (not turbo)	£115	£95
HIF44 Turbo	£135	£150
Twin HIF4	£215	£125
Twin HIF6	£215	£150
Twin HD4/6/8	£595	POA
Triple HD8	£895	POA

Includes:

- Fully dismantled
- Chemically cleaned, non-abrasive barrel clean
- Thorough health inspection of all components
- Bodies re-bushed
- Reassembled with new throttle shafts, butterflies, jets, needle valves, gaskets, seals
- Reset to factory settings

Additional Services	
Dashpot Polishing Single	£8
Dashpot Polishing Twin	£13
Line Reaming and Fitting New Shaft Bushes	£19 (Assumes carb is already stripped)
Courier Service	
UK	£7.95
Europe	From £29
Rest of World	From £39

N.B we are unable to provide technical support for installation and tuning. It is assumed that the carb(s) will be fitted and setup by a qualified mechanic with experience of classic carburettor tuning and access to CO emissions machine and timing strobe. Where deviating from the factory installed engine or carburettor specification for the vehicle, rolling road tuning is essential to determine correct metering needle(s) for the application

*****TRADE ENQUIRIES WELCOME*****

Fix A Carb Ltd
52 Eastgate
Station Approach
Woking
GU22 7PQ
Tel: 07875300056
Email: sales@fixacarb.co.uk

***Where incomplete or physically damaged carbs are supplied to us for restoration partial surcharges will apply.

*****TRADE ENQUIRIES WELCOME*****